

S.W. 1/4
SECTION 32, T.6N., R.2W., S.L.B.&M.

85

TAXING UNIT 53

TAYLOR DISTRICT

PREFIX 15-085

SCALE 1"=200'

WEST WEBER-TAYLOR CEMETERY MAINTENANCE DISTRICT
TAYLOR-WEST WEBER WATER IMPROVEMENT DISTRICT

SEE PAGE 86

H. V. PETERSON INVESTMENT CO.

0010

TU 53

28 AC±

RANCHO DEL LAGO SUBDIVISION NO. 4

RANCHO DEL LAGO
SUB. NO. 3

3000 SO. ST.

3000 S. ST.

SEE PAGE 187

SEE PAGE 178

N. 89° 25' 42" W.

1385.57'

800.00'

HANSEN FAMILY LIMITED
PARTNERSHIP

0006

TU 53

30 CHS.

15.59 AC±

2190'

0004

TU 53

37.67 AC

2350'

0002

TU 53

34.65 AC±

VERNAL E
ANDERSON
TRUSTEE

0001

TU 53

3300

SOUTH

STREET

SEE BOOK 8, PAGE 37

SEE PAGE
82

SEE PAGE
84