

SECTION 14, T.7N., R.2W., S.L.B.&M.


2

TOWN OF PLEASANT VIEW, FARR WEST CITY & PLEASANT VIEW DISTRICT

TAXING UNITS: 01, 04, 11, 45, 83

SCALE 1" = 400'

PREFIX: 19-002



SEE PAGE

3

SEE PAGE

1

SEE PAGE 11

SEE PAGE 11-1

R.B. 5-70